

- **Missing Shortcut on Desktop**

- Solution: Create new Shortcut
- Go to C:\M2000 folder
- Right click on MT2000.exe or Application
  - Click on “Sent to” (might have to pick “other options”)
  - Click “Desktop (create shortcut)”